Page 1

January 08, 2010 1:24:09 PM

Required Date: 1/18/2010

Item ID:

D3979-1

Accept



Setup Start



**Revision ID:** 

Item Name: **Start Date:** 

Washer

QC:

1/11/2010

**Start Qty: 10.00** Req'd Qty: 10.00

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

MP

Date: 10-01-08 Tooling:

Date:

SPC (Y/N):

Date:

Date:

Rev.

Run

Start

Stop

Stop

Sequence ID/ **Work Center ID**  Operation Description

**Revision Nbr** 

Set Up/ **Run Hours**  Draw Number Draw Plan Code

Accept Qty

Reject Qty

B 10-1-B

Reject Insp. Number Stamp

: D3979

Draw Nbr

Α

Waterjet

100

FLOW CNC Waterjet

861. 126

Memo

0.00

0.00

Dwg Rev: Prog Rev:

1-Cut as per Dwg D3979

2-Deburr if necessary

Deburr Mit 10/01/19

110

QC2- Inspect parts off machine FAI/FAIB

0.00

QC

Memo

0.00

R10-1-13

Quality Control

	•								
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·							
								_	
Part No	:	PAR #:	Fault Categ	gory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	
Resolution		esolution:	Disposition	<b>:</b>	_ QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR	1)			
		Description of NC	Corrective Action Section		Veritic		cation	ation Approval	Approval
DATE	STEP	STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		tion C	Chief Eng	QC Inspector
						÷			
					Ì				

January 08, 2010 1:24:09 PM

Required Date: 1/18/2010

Page 2

Item ID:

D3979-1

Accept

Setup Start



**Revision ID:** 

Item Name: **Start Date:** 

Washer

1/11/2010

**Start Qty: 10.00** Req'd Qty: 10.00

Operation

Description

**Cust Item ID:** 

**Customer:** 

Reference:

**Approvals:** 

Process Plan:

Date:

**Tooling:** 

Date:

Rev.

Run

Start

Stop

Stop

QC: \_\_\_\_

Date: SPC (Y/N):

Date:

Draw

Sequence ID/

Work Center ID

120

Memo

Set Up/ Run Hours

Number

Draw Plan Code

Accept Qty

Reject Qty

Reject Number Stamp

Insp.

Quality Control

QC8- Inspect parts - second check

0.00

0.00

witto

130

HandFinish

Hand Finishing

Chemical Conversion Coat per QSI005 4.1

Memo

=> M 10/01/21

0.00

140

Quality Control

QC3- Inspect Part Finish

Memo

0.00 / 10-00 21

Dart Aerosp	ace Ltd
-------------	---------

W/O:			W	ORK ORDER CHANG	GES					
DATE	DATE STEP P			JRE CHANGE By			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
- No.										
			,							
Part No	•	PAR #:	Fault Cat	egory:	NCR	: Yes N	lo <b>DQ</b>	<b>4</b> :	Date:	
Resolution:			Disposition: Q			N/C Clo	sed:		Date: _	
NCR:			WORK ORI	DER NON-CONFORM	IANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial	Action Description	ction B	Sign &	Verific Section		Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng		Date				
l			1				1		1	

#### Work Order ID 55183

January 08, 2010 1:24:09 PM



Page 3

Item ID:

D3979-1

Accept

Setup Start

Stop



**Revision ID:** 

Item Name: **Start Date:** 

Washer

1/11/2010

**Start Qty: 10.00** 

Operation

Description

**Reg'd Oty:** 10.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Draw

Rev.

Plan

Code

Start

Stop

**Required Date: 1/18/2010** 

QC:

Date:\_\_\_\_\_

SPC (Y/N):

Set Up/

**Run Hours** 

Date:

Accept

Qty

Run

Reject

Reject Number

Insp. Stamp

Sequence ID/ **Work Center ID** 

150

Packaging Packaging

Memo

Memo

0.00

0.00

Draw

Number

Qty

160

QC21- Final Inspection - Work Order Release

Identify as per dwg & Stock Location: 105

0.00

0.00

Quality Control

W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·					
Part No	:	PAR #:	Fault Categ	jory:	_ NCR: Yes	No DQ	A:	_ Date: _	
	Re	solution:	Disposition	1:	_ QA: N/C (	Closed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)			
DATE	STED	Description of NC			on B	Verifi	cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description  Chief Eng	Sign Date	& Sec	Section C	Chief Eng	QC Inspector
i									
٠.									

#### **Picklist Print**

January 08, 2010 1:24:09 PM

Work Order ID: 55183

D3979-1 Parent Item:

Parent Item Name:

Washer

Comments:

IPP RevA: New issue DD verified by:EC

**Start Date: 1/11/2010** 

Required Date: 1/18/2010

Page 1

Status

**Start Qty: 10.00** 

Required Qty: 10.00

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued
M6061T6S.125		Purchased	No			100	sf	136.1823	0.1284		

6061-T6 .125 Sheet

on Otro	Los Codo

Warehouse Loc Qty Loc Code Location Main Warehouse MAT 136.1823 110062 1.85 111642 19.592 112476 32 112567 18.7403 113424 113424 64



1R 10-1-3

W/O:			WO	RK ORDER CHAN	GES					
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	/	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·								
				· · · · · · · · · · · · · · · · · · ·						
Part No	•	PAR #:	Fault Categ	ory:	NCR: Y	es N	o <b>DQA</b> :		_ Date: _	
Resolution:			Disposition	•	QA: N/0	C Clos	sed:		Date:	
NCR:			WORK ORDE	R NON-CONFORM	MANCE (N	ICR)				e necto
DATE	STEP	Description of NC	Corrective Action Initial Action Descrip		ection B	gn &	Verifica		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		ate	Section	С	Chief Eng	QC Inspector
	,									
									ļ	

DART AEROSPACE LTD	Work Order:	55183
Description: WACHER	Part Number:	D3979-1
Inspection Dwg: D 3979-1 Rev: A		Page 1 of 1


# FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø .88	100010. +	1881	7			
1 .405	4- 010	408	8	٠		
.135	7/_ ,010	1784	*			
				ļ		
			ļ			
	·					
				<u> </u>		
			<u> </u>			· .
				<b></b>		
		·		-		
			1			

Measured by:	102	Audited by:	Prototype Approval:	N/A
Date:		Date: 10/01/20	Date:	N/A

Rev	Date	Change Revised by	y Approved
Α		New Issue KJ/JLM	



W/O:			WC	RK ORDER CHANGES	= 4,4 = .				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							'	<u>.</u>	
i									
Part No	:	PAR #:	Fault Cate	gory: N	ICR: Yes	No <b>DQ</b>	<b>A</b> :	Date:	
Resolution:		esolution:	Disposition: C			losed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMAN	CE (NCI	7)			
DATE				Corrective Action				1	T
	STED	Description of NC		Corrective Action Section B		Verific	cation	Approval	Approval
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description  Chief Eng	Sign Date	&   Secti	cation on C	Approval Chief Eng	Approval QC Inspector
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	&   Secti			
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	&   Secti			
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	&   Secti			
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	&   Secti			
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	&   Secti			
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	&   Secti			

H:\tFQRMS\Quality Assurance\approved QA\NCRWO RevE